

Tech Tips Index

Authors

- Armstrong, John N., "D-Meter Resolution with an Analog Display," *M.E.*, Vol. 54, 1996, p. 816.
- Berry, Francis R., "RT Problem," *Tech Hints, M.E.*, Vol. 37, July 1979, p. 58.
- Boyer, Andrew, "Easy Radiographic Identification," *M.E.*, Vol. 59, 2001, p. 880.
- Boyer, Andrew, "Flexible Radiographic Film Cassette Holder," *M.E.*, Vol. 58, 2000, p. 427.
- Burkle, W.S., "Nomogram for Calculating Ultrasonic Sound Beam Spread," *Tech Hints, M.E.*, Vol. 40, 1982, p. 50.
- Burkle, William S. and James O. Lightfoot, "A Nomogram for Calculating Intensity and Distance Relationships in Accordance with the Inverse Square Law," *Tech Hints, M.E.*, Vol. 39, 1981, p. 796.
- Burleigh, Douglas D., "Practical (Nontechnical) Aspects of NDT, Using Thermographic NDT as an Example," *M.E.*, Vol. 54, 1996, p. 1266.
- Burns, Alistair, "Hands Free Ultrasonic Testing in Cramped Spaces," *M.E.*, Vol. 61, 2003, p. 140.
- Carey, Joseph M., "Difficulty Demagnetizing?," *M.E.*, Vol. 59, 2001, p. 793.
- Clark, Robert F., "Resolving Inaccessible Back Surfaces during Ultrasonic Testing," *M.E.*, Vol. 60, 2002, p. 1033.
- Crawford, Grant, "Processing Material Loss in Close Tolerance Holes," *M.E.*, Vol. 58, 2000, p. 1383.
- Crowe, George, "Improving Radiographic Contrast on Barely Visible Corrosion in Aircraft Structures," *M.E.*, Vol. 59, 2001, p. 1178.
- Davis, Jim, "Penetrometer Density Chart," *Tech Hints, M.E.*, Vol. 38, May 1980, p. 20.
- Doyle, J.C., "Low Profile Wire Splice," *M.E.*, Vol. 57, 1999, p. 443.
- DuBosc, P., "Photographs of Reference Test Panels for Fluorescent Penetrant Testing," *M.E.*, Vol. 60, 2002, p. 703.
- Engelbart, Roger W., "Acid Etching — An Alternative for Localized Penetrant Inspection," *M.E.*, Vol. 53, 1995, p. 402.
- France, John J., "UT Problem," *Tech Hints, M.E.*, Vol. 37, April 1979, p. 32.
- Gerhard, Richard, "Accurate Source Location," *M.E.*, Vol. 54, 1996, p. 1024.
- Grajeda, Maria, "Maintain Water-Based MT Bath Solution with a Refractometer," *M.E.*, Vol. 55, 1997, p. 666.
- Grover, Paul and Craig K. Kelch, "Infrared Thermography Identifies Damaged Capacitors," *M.E.*, Vol. 54, 1996, p. 587.
- Hagemaiier, Don, "Failure of the X-ray Inverse Square Law," *M.E.*, Vol. 62, 2004, p. 1131.
- Hands, Godfrey, "Magic Magnets," *M.E.*, Vol. 54, 1996, p. 422.
- Hands, Godfrey, "Simple Low-Cost Ultrasonic Plotter," *M.E.*, Vol. 53, 1995, p. 1278.
- Hands, Godfrey, "Watch Where You're Going," *M.E.*, Vol. 53, 1995, p. 588.
- Hansen, Shannon J., "Foreign Part Retrievals," *M.E.*, Vol. 54, 1996, p. 1024.
- Henzel, Claude S., "A Tech Tip Sample," *M.E.*, Vol. 53, 1995, p. 126.
- Henke, George, *Tech Hints, M.E.*, Vol. 38, January 1980, p. 42.
- Henke, George, "Battery Extractor," *M.E.*, Vol. 56, 1998, p. 1205.
- Henke, George, "Cal Block Blocks," *M.E.*, Vol. 53, 1995, p. 819.
- Henke, George, "Coaxial Cable Problem," *Tech Hints, M.E.*, Vol. 36, December 1978, p. 31.
- Henke, George, "Code Problems?," *Tech Hints, M.E.*, Vol. 38, April 1980, p. 49.
- Henke, George, "Index Marks Made Easy," *M.E.*, Vol. 53, 1995, p. 716.
- Henke, George, "MT Problem," *Tech Hints, M.E.*, Vol. 36, September 1978, p. 84.
- Henke, George, "MT Problem," *Tech Hints, M.E.*, Vol. 37, March 1979, p. 39.
- Henke, George, "Penetrant Dye Removal," *M.E.*, Vol. 56, 1998, p. 969.
- Henke, George, "Protected Centrifuge Tube," *M.E.*, Vol. 57, 1999, p. 660.
- Henke, George, "Radiograph Size Indicator," *M.E.*, Vol. 55, 1997, p. 804.
- Henke, George, "RT Enlargement/Flaw Sizing," *M.E.*, Vol. 55, 1997, p. 986.
- Henke, George, "RT Problem," *Tech Hints, M.E.*, Vol. 36, August 1978, p. 53.
- Henke, George, "RT Problem," *Tech Hints, M.E.*, Vol. 36, October 1978, p. 56.
- Henke, George, "RT Problem," *Tech Hints, M.E.*, Vol. 36, November 1978, p. 21.
- Henke, George, "RT Problem," *Tech Hints, M.E.*, Vol. 38, July 1980, p. 55.
- Henke, George, "RT Subject Contrast," *M.E.*, Vol. 53, 1995, p. 588.
- Henke, George, "Search Unit Adapter," *M.E.*, Vol. 54, 1996, p. 422.
- Henke, George, "Specific Angle Protractor," *M.E.*, Vol. 61, 2003, p. 484.
- Henke, George, "Straight Arrow," *M.E.*, Vol. 53, 1995, p. 1377.
- Henke, George, "Straight Beam Index Point," *M.E.*, Vol. 54, 1996, p. 814.
- Henke, George, "Tie Your Cables," *M.E.*, Vol. 56, 1998, p. 1390.
- Henke, George, "'Unrock' Your Search Unit," *M.E.*, Vol. 55, 1997, p. 1233.
- Henke, George, Untitled, *M.E.*, Vol. 56, 1998, p. 82.
- Henke, George, "UT Angles," *M.E.*, Vol. 53, 1995, p. 588.
- Henke, George, "U/T Problem," *Tech Hints, M.E.*, Vol. 36, June 1978, p. 71.
- Henke, George, "UT Problem," *Tech Hints, M.E.*, Vol. 37, January 1979, p. 61.
- Hoff, Arthur, "Determining Braze Coverage," *M.E.*, Vol. 59, 2001, p. 979.
- Hoff, Arthur, "Easier Part Identification," *M.E.*, Vol. 57, 1999, p. 934.
- Hoff, Arthur, "Guaranteed Exposure," *M.E.*, Vol. 58, 2000, p. 977.
- Hoff, Arthur, "Multiple Radiographs Using a Single Film," *M.E.*, Vol. 57, 1999, p. 830.
- Hurst, Terry, "Penetrant and Magnetic Particle Proof," *M.E.*, Vol. 53, 1995, p. 488.
- Irvine, Arthur W., "Quick and Easy Disbond Location," *M.E.*, Vol. 53, 1995, p. 1278.
- Irvine, Arthur W., "Quick Eddy Current Inspection of Aircraft Wheels," *M.E.*, Vol. 55, 1997, p. 573.
- Irvine, Arthur W., "Ultrasonic Testing in a Tight Spot," *M.E.*, Vol. 55, 1997, p. 1153.
- Jackson, Charles N., Jr., "Smart Dollars — Those Saved While Helium Leak Testing," *Tech Hints, M.E.*, Vol. 42, 1984, p. 1076.
- Jackson, Charlie, "Helium Leak Test Aid," *Tech Hints, M.E.*, Vol. 40, 1982, p. 286.

- Kelch, Craig K., see Grover, Paul, *M.E.*, Vol. 54, 1996, p. 587.
- King, William, "Immersion UT Offset Calculation," *M.E.*, Vol. 61, 2003, p. 865.
- Kleven, Stuart, "Balloon-Aided Radiography," *M.E.*, Vol. 54, 1996, p. 587.
- Kleven, Stuart, "Cutting Signal Confusion," *M.E.*, Vol. 54, 1996, p. 52.
- Klosterman, Edward, see Kropas-Hughes, Claudia, *M.E.*, Vol. 60, 2002, p. 90.
- Kropas-Hughes, Claudia and Edward Klosterman, "A Simple Method to Examine the Alignment of a Residual Stress Measuring X-Ray Diffractometer," *M.E.*, Vol. 60, 2002, p. 90.
- Kulchitsky, Gerald, "Enhancing the Repeatability and Consistency of the Tool Steel Test Ring," *M.E.*, Vol. 61, 2003, p. 8.
- Lachermeier, Randy, "Extendable UT Cable," *M.E.*, Vol. 53, 1995, p. 1179.
- Lachermeier, Randy, "Flat Bottomed Hole Verification," *M.E.*, Vol. 54, 1996, p. 587.
- Larkin, Tom, "Dealing with Particle Concentration," *M.E.*, Vol. 59, 2001, p. 1087.
- Levine, Arthur, "An Alternative to Expensive Dip Tubs," *M.E.*, Vol. 57, 1999, p. 366.
- Lightfoot, James O., see Burkle, William S., *M.E.*, Vol. 39, 1981, p. 796.
- Lord, Claude, "Presenting Radiography to Larger Audiences," *M.E.*, Vol. 59, 2001, p. 1278.
- Lord, Claude, "Two NDT Uses for Tape," *M.E.*, Vol. 53, 1995, p. 1179.
- Mace, Daniel, "High Contrast without the Paint," *M.E.*, Vol. 53, 1995, p. 898.
- Mace, Daniel, "X-Ray Centering with a Laser Pointer," *M.E.*, Vol. 57, 1999, p. 1069.
- Makarwich, I. Byron, "Arcing Prevention," *M.E.*, Vol. 58, 2000, p. 796.
- Marks, Dan, "Finding a Third Hand," *M.E.*, Vol. 54, 1996, p. 1397.
- Marks, Dan, "Make Your Own Ultrasonic Calculator," *M.E.*, Vol. 54, 1996, p. 814-816.
- Marks, Dan, "Positive ID," *M.E.*, Vol. 53, 1995, p. 1377.
- Massie, Terry, "Easy Marker Removal," *M.E.*, Vol. 53, 1995, p. 898.
- McKinney, W.E.J., "Developer Control," *M.E.*, Vol. 53, 1995, p. 1013.
- Morris, John, "Cotton Swab and Nonaqueous Developer," *M.E.*, Vol. 56, 1998, p. 1285.
- Morris, John, "Cotton Swab and Nonaqueous Developer," *M.E.*, Vol. 58, 2000, p. 547.
- Morris, John, "Magnetic Particle Central Bar Conductors," *M.E.*, Vol. 57, 1999, p. 1162.
- Morris, John, "Magnetic Particle Testing," *M.E.*, Vol. 58, 2000, p. 1304.
- Murren, Con, "How Do You Measure UV?" *M.E.*, Vol. 55, 1997, p. 986.
- Perrin, Bill, "Antispill Film Identification Wallet," *M.E.*, Vol. 58, 2000, p. 869.
- Perrin, Bill, "A Shot of Couplant," *M.E.*, Vol. 54, 1996, p. 52.
- Perrin, Bill, "Easier Handling of Acrylic Distance Amplitude Curve Templates," *M.E.*, Vol. 59, 2001, p. 610.
- Perrin, Bill, "Easy Equipment Storage," *M.E.*, Vol. 56, 1998, p. 1004.
- Perrin, Bill, "No More Tangled Lines," *M.E.*, Vol. 55, 1997, p. 804.
- Perrin, Bill, "Temporary Parts Dryer," *M.E.*, Vol. 60, 2002, p. 552.
- Plumstead, Robert F., "Manual Processing of Pipe Weld Radiographs," *M.E.*, Vol. 53, 1995, p. 1278.
- Plumstead, William C., "A New Angle for Weld Inspection," *M.E.*, Vol. 53, 1995, p. 488.
- Plumstead, William C., "Consistent Elliptical Exposures," *M.E.*, Vol. 60, 2002, p. 614.
- Plumstead, William C., "Damp Cloth in Sealable Plastic Bags for Removal of Excess Water Washable Penetrant," *M.E.*, Vol. 60, 2002, p. 149.
- Plumstead, William C., "Foolproof Radiographic Exposures," *M.E.*, Vol. 55, 1997, p. 1153.
- Plumstead, William C., "Removal of Excess Liquid Penetrant on Rough Surfaces," *M.E.*, Vol. 59, 2001, p. 1376.
- Plumstead, William C., "Second Cassette to Assure Correct Long Exposures," *M.E.*, Vol. 60, 2002, p. 420.
- Saunders, Robert, "Hanging on to Tricky Transducers," *M.E.*, Vol. 53, 1995, p. 488.
- Sherlock, Charles N., *Tech Hints*, *M.E.*, Vol. 37, August 1979, p. 58.
- Sherlock, Charles N., *Tech Hints*, *M.E.*, Vol. 37, November 1979, p. 30.
- Stanley, Alton, "Hold That Film," *M.E.*, Vol. 54, 1996, p. 52.
- Staton, Jean, see Viaclovsky, Syl, *M.E.*, Vol. 58, 2000, p. 645.
- Taha, Albert, "Don't Settle for Less," *M.E.*, Vol. 53, 1995, p. 1377.
- Tiefenauer, Richard L., "Ultrasonic Couplants," *M.E.*, Vol. 55, 1997, p. 192.
- Trotter, Ed, "Radiographic Sensitivity Determination," *M.E.*, Vol. 60, 2002, p. 1358.
- Tyson, John, "Tip for the ESPI/Shearography Inspection," *M.E.*, Vol. 57, 1999, p. 443.
- Viaclovsky, Syl and Jean Staton, "Reducing Streaks on Processed Film," *M.E.*, Vol. 58, 2000, p. 645.
- Wade, Nathan, "Radiography of Test Coupons," *M.E.*, Vol. 61, 2003, p. 1125.
- Woollven, John, "Gamma Radiography — No Longer a Pain in the Back," *M.E.*, Vol. 54, 1996, p. 816.
- Woollven, John, "Timing Your Defect Locations," *M.E.*, Vol. 54, 1996, p. 422.
- Zoofan, Bahman, "Accurate Scaling of Magnified Microfocus Radiographs," *M.E.*, Vol. 60, 2002, p. 867.
- Zoofan, Bahman, "Creating Laminations for Ultrasonic Testing Training Purposes," *M.E.*, Vol. 60, 2002, p. 1156.
- Zoofan, Bahman, "Determining Weld Toe and Centerline Location in Butt Weld Radiography," *M.E.*, Vol. 60, 2002, p. 1420.
- Zoofan, Bahman, "Elliptical Exposures Revisited," *M.E.*, Vol. 60, 2002, p. 961.
- Zoofan, Bahman, "Estimating Volume When Replenishing Developer for Film Radiography," *M.E.*, Vol. 61, 2003, p. 1212.
- Zoofan, Bahman, "Masking Radiographs," *M.E.*, Vol. 61, 2003, p. 409.
- Zoofan, Bahman, "Measuring Discontinuity Depth of Butt Welds," *M.E.*, Vol. 62, 2004, p. 59.
- Zoofan, Bahman, "Radiography and Planar Discontinuities," *M.E.*, Vol. 63, 2005, p. 821.
- Zoofan, Bahman, "Stabilizing Radiographic Film in Pipes," *M.E.*, Vol. 61, 2003, p. 588.
- Zoofan, Bahman, "Using Intensifier Screens to Secure Film," *M.E.*, Vol. 61, 2003, p. 924.

Titles and Keywords

- "Accurate Scaling of Magnified Microfocus Radiographs," Bahman Zoofan, *M.E.*, Vol. 60, 2002, p. 867.
- "Accurate Source Location," Richard Gerhard, *M.E.*, Vol. 54, 1996, p. 1024.
- "Acid Etching — An Alternative for Localized Penetrant Inspection," Roger W. Engelbart, *M.E.*, Vol. 53, 1995, p. 402.

"Aircraft Structures, Improving Radiographic Contrast on Barely Visible Corrosion in," George Crowe, *M.E.*, Vol. 59, 2001, p. 1178.

"Aircraft Wheels, Quick Eddy Current Inspection of," Arthur W. Irvine, *M.E.*, Vol. 55, 1997, p. 573.

"Alignment of a Residual Stress Measuring X-Ray Diffractometer, A Simple Method to Examine the," Claudia Kropas-Hughes and Edward Klosterman, *M.E.*, Vol. 60, 2002, p. 90.

"An Alternative to Expensive Dip Tubs," Arthur Levine, *M.E.*, Vol. 57, 1999, p. 366.

"A New Angle for Weld Inspection," William C. Plumstead, *M.E.*, Vol. 53, 1995, p. 488.

"A Nomogram for Calculating Intensity and Distance Relationships in Accordance with the Inverse Square Law," William S. Burkle and James O. Lightfoot, *Tech Hints*, *M.E.*, Vol. 39, 1981, p. 796.

"Angles, UT," George Henke, *M.E.*, Vol. 53, 1995, p. 588.

"Antispill Film Identification Wallet," Bill Perrin, *M.E.*, Vol. 58, 2000, p. 869.

"Arcing Prevention," I. Byron Makarwich, *M.E.*, Vol. 58, 2000, p. 796.

"Arrow, Straight," George Henke, *M.E.*, Vol. 53, 1995, p. 1377.

"A Shot of Couplant," Bill Perrin, *M.E.*, Vol. 54, 1996, p. 52.

"A Simple Method to Examine the Alignment of a Residual Stress Measuring X-Ray Diffractometer," Claudia Kropas-Hughes and Edward Klosterman, *M.E.*, Vol. 60, 2002, p. 90.

"A Tech Tip Sample," Claude S. Hendzel, *M.E.*, Vol. 53, 1995, p. 126.

"Balloon-Aided Radiography," Stuart Kleven, *M.E.*, Vol. 54, 1996, p. 587.

"Battery Extractor," George Henke, *M.E.*, Vol. 56, 1998, p. 1205.

"Block Blocks, Cal," George Henke, *M.E.*, Vol. 53, 1995, p. 819.

"Brazing Coverage, Determining," Arthur Hoff, *M.E.*, Vol. 59, 2001, p. 979.

"Cables, Tie Your," George Henke, *M.E.*, Vol. 56, 1998, p. 1390.

"Cal Block Blocks," George Henke, *M.E.*, Vol. 53, 1995, p. 819.

"Capacitors, Infrared Thermography Identifies Damaged," Paul Grover and Craig K. Kelch, *M.E.*, Vol. 54, 1996, p. 587.

"Cassette to Assure Correct Long Exposures, Second," William C. Plumstead, *M.E.*, Vol. 60, 2002, p. 420.

"Centering with a Laser Pointer, X-Ray," Daniel Mace, *M.E.*, Vol. 57, 1999, p. 1069.

"Central Bar Conductors, Magnetic Particle," John Morris, *M.E.*, Vol. 57, 1999, p. 1162.

"Centrifuge Tube, Protected," George Henke, *M.E.*, Vol. 57, 1999, p. 660.

"Close Tolerance Holes, Processing Material Loss in," Grant Crawford, *M.E.*, Vol. 58, 2000, p. 1383.

"Conductors, Magnetic Particle Central Bar," John Morris, *M.E.*, Vol. 57, 1999, p. 1162.

"Consistent Elliptical Exposures," William C. Plumstead, *M.E.*, Vol. 60, 2002, p. 614.

"Contrast on Barely Visible Corrosion in Aircraft Structures, Improving Radiographic," George Crowe, *M.E.*, Vol. 59, 2001, p. 1178.

"Contrast, RT Subject," George Henke, *M.E.*, Vol. 53, 1995, p. 588.

"Contrast without the Paint, High," Daniel Mace, *M.E.*, Vol. 53, 1995, p. 898.

"Corrosion in Aircraft Structures, Improving Radiographic Contrast on Barely Visible," George Crowe, *M.E.*, Vol. 59, 2001, p. 1178.

"Cotton Swab and Nonaqueous Developer," John Morris, *M.E.*, Vol. 56, 1998, p. 1285.

"Cotton Swab and Nonaqueous Developer," John Morris, *M.E.*, Vol. 58, 2000, p. 547.

"Couplant, A Shot of," Bill Perrin, *M.E.*, Vol. 54, 1996, p. 52.

"Couplants, Ultrasonic," Richard L. Tiefenauer, *M.E.*, Vol. 55, 1997, p. 192.

"Creating Laminations for Ultrasonic Testing Training Purposes," Bahman Zoofan, *M.E.*, Vol. 60, 2002, p. 1156.

"Cutting Signal Confusion," Stuart Kleven, *M.E.*, Vol. 54, 1996, p. 52.

"Damp Cloth in Sealable Plastic Bags for Removal of Excess Water Washable Penetrant," William C. Plumstead, *M.E.*, Vol. 60, 2002, p. 149.

"Dealing with Particle Concentration," Tom Larkin, *M.E.*, Vol. 59, 2001, p. 1087.

"Defect Locations, 'Timing' Your," John Woollven, *M.E.*, Vol. 54, 1996, p. 422.

"Demagnetizing, Difficulty?," Joseph M. Carey, *M.E.*, Vol. 59, 2001, p. 793.

"Determining Braze Coverage," Arthur Hoff, *M.E.*, Vol. 59, 2001, p. 979.

"Determining Weld Toe and Centerline Location in Butt Weld Radiography," Bahman Zoofan, *M.E.*, Vol. 60, 2002, p. 1420.

"Developer Control," W.E.J. McKinney, *M.E.*, Vol. 53, 1995, p. 1013.

"Developer, Cotton Swab and Nonaqueous," John Morris, *M.E.*, Vol. 56, 1998, p. 1285.

"Developer, Cotton Swab and Nonaqueous," John Morris, *M.E.*, Vol. 58, 2000, p. 547.

"Difficulty Demagnetizing?," Joseph M. Carey, *M.E.*, Vol. 59, 2001, p. 793.

"Diffractometer, A Simple Method to Examine the Alignment of a Residual Stress Measuring X-Ray," Claudia Kropas-Hughes and Edward Klosterman, *M.E.*, Vol. 60, 2002, p. 90.

"Dip Tubs, An Alternative to Expensive," Arthur Levine, *M.E.*, Vol. 57, 1999, p. 366.

"Disbond Location, Quick and Easy," Arthur W. Irvine, *M.E.*, Vol. 53, 1995, p. 1278.

"Distance Amplitude Curve Templates, Easier Handling of Acrylic," Bill Perrin, *M.E.*, Vol. 59, 2001, p. 610.

"D-Meter Resolution with an Analog Display," John N. Armstrong, *M.E.*, Vol. 54, 1996, p. 816.

"Don't Settle for Less," Albert Taha, *M.E.*, Vol. 53, 1995, p. 1377.

"Dye Removal, Penetrant," George Henke, *M.E.*, Vol. 56, 1998, p. 969.

"Easier Handling of Acrylic Distance Amplitude Curve Templates," Bill Perrin, *M.E.*, Vol. 59, 2001, p. 610.

"Easier Part Identification," Arthur Hoff, *M.E.*, Vol. 57, 1999, p. 934.

"Easy Equipment Storage," Bill Perrin, *M.E.*, Vol. 56, 1998, p. 1004.

"Easy Marker Removal," Terry Massie, *M.E.*, Vol. 53, 1995, p. 898.

"Easy Radiographic Identification," Andrew Boyer, *M.E.*, Vol. 59, 2001, p. 880.

"Eddy Current Inspection of Aircraft Wheels, Quick," Arthur W. Irvine, *M.E.*, Vol. 55, 1997, p. 573.

"Elliptical Exposures Revisited," Bahman Zoofan, *M.E.*, Vol. 60, 2002, p. 961.

"Enhancing the Repeatability and Consistency of the Tool Steel Test Ring," Gerald Kulchitsky, *M.E.*, Vol. 61, 2003, p. 8.

"Equipment Storage, Easy," Bill Perrin, *M.E.*, Vol. 56, 1998, p. 1004.

"ESPI/Shearography Inspection, Tip for the," John Tyson, *M.E.*, Vol. 57, 1999, p. 443.

"Estimating Volume When Replenishing Developer for Film Radiography," Bahman Zoofan, *M.E.*, Vol. 61, 2003, p. 1212.

"Exposure, Guaranteed," Arthur Hoff, *M.E.*, Vol. 58, 2000, p. 977.

"Exposures, Second Cassette to Assure Correct Long," William C. Plumstead, *M.E.*, Vol. 60, 2002, p. 420.

"Extendable UT Cable," Randy Lachermeier, *M.E.*, Vol. 53, 1995, p. 1179.

"Failure of the X-ray Inverse Square Law," Don Hagemeyer, *M.E.*, Vol. 62, 2004, p. 1131.

"Film Cassette Holder, Flexible Radiographic," Andrew Boyer, *M.E.*, Vol. 58, 2000, p. 427.

"Film, Hold That," Alton Stanley, *M.E.*, Vol. 54, 1996, p. 52.

"Film Identification Wallet, Antispill," Bill Perrin, *M.E.*, Vol. 58, 2000, p. 869.

"Film, Multiple Radiographs Using a Single," Arthur Hoff, *M.E.*, Vol. 57, 1999, p. 830.

"Film, Reducing Streaks on Processed," Syl Viaclovsky and Jean Staton, *M.E.*, Vol. 58, 2000, p. 645.

"Finding a Third Hand," Dan Marks, *M.E.*, Vol. 54, 1996, p. 1397.

"Flat Bottomed Hole Verification," Randy Lachermeier, *M.E.*, Vol. 54, 1996, p. 587.

"Flaw Sizing, RT Enlargement /," George Henke, *M.E.*, Vol. 55, 1997, p. 986.

"Flexible Radiographic Film Cassette Holder," Andrew Boyer, *M.E.*, Vol. 58, 2000, p. 427.

"Foolproof Radiographic Exposures," William C. Plumstead, *M.E.*, Vol. 55, 1997, p. 1153.

"Foreign Part Retrievals," Shannon J. Hansen, *M.E.*, Vol. 54, 1996, p. 1024.

"Gamma Radiography — No Longer a Pain in the Back," John Woollven, *M.E.*, Vol. 54, 1996, p. 816.

"Guaranteed Exposure," Arthur Hoff, *M.E.*, Vol. 58, 2000, p. 977.

"Hands Free Ultrasonic Testing in Cramped Spaces," Alistair Burns, *M.E.*, Vol. 61, 2003, p. 140.

"Hanging on to Tricky Transducers," Robert Saunders, *M.E.*, Vol. 53, 1995, p. 488.

"Helium Leak Test Aid," Charlie Jackson, *Tech Hints, M.E.*, Vol. 40, 1982, p. 286.

"High Contrast without the Paint," Daniel Mace, *M.E.*, Vol. 53, 1995, p. 898.

"Hold That Film," Alton Stanley, *M.E.*, Vol. 54, 1996, p. 52.

"Holes, Processing Material Loss in Close Tolerance," Grant Crawford, *M.E.*, Vol. 58, 2000, p. 1383.

"Hole Verification, Flat Bottomed," Randy Lachermeier, *M.E.*, Vol. 54, 1996, p. 587.

"How Do You Measure UV?," Con Murren, *M.E.*, Vol. 55, 1997, p. 986.

"Identification, Easier Part," Arthur Hoff, *M.E.*, Vol. 57, 1999, p. 934.

"Identification, Easy Radiographic," Andrew Boyer, *M.E.*, Vol. 59, 2001, p. 880.

"ID, Positive," Dan Marks, *M.E.*, Vol. 53, 1995, p. 1377.

"Immersion UT Offset Calculation," William King, *M.E.*, Vol. 61, 2003, p. 865.

"Improving Radiographic Contrast on Barely Visible Corrosion in Aircraft Structures," George Crowe, *M.E.*, Vol. 59, 2001, p. 1178.

"Index Marks Made Easy," George Henke, *M.E.*, Vol. 53, 1995, p. 716.

"Index Point, Straight Beam," George Henke, *M.E.*, Vol. 54, 1996, p. 814.

"Infrared Thermography Identifies Damaged Capacitors," Paul Grover and Craig K. Kelch, *M.E.*, Vol. 54, 1996, p. 587.

"Laser Pointer, X-Ray Centering with a," Daniel Mace, *M.E.*, Vol. 57, 1999, p. 1069.

"Lines, No More Tangled," Bill Perrin, *M.E.*, Vol. 55, 1997, p. 804.

"Liquid Penetrant on Rough Surfaces, Removal of Excess," William C. Plumstead, *M.E.*, Vol. 59, 2001, p. 1376.

"Low Profile Wire Splice," J.C. Doyle, *M.E.*, Vol. 57, 1999, p. 443.

"Magic Magnets," Godfrey Hands, *M.E.*, Vol. 54, 1996, p. 422.

"Magnetic Particle Central Bar Conductors," John Morris, *M.E.*, Vol. 57, 1999, p. 1162.

"Magnetic Particle Proof, Penetrant and," Terry Hurst, *M.E.*, Vol. 53, 1995, p. 488.

"Magnetic Particle Testing," John Morris, *M.E.*, Vol. 58, 2000, p. 1304.

"Magnets, Magic," Godfrey Hands, *M.E.*, Vol. 54, 1996, p. 422.

"Maintain Water-Based MT Bath Solution with a Refractometer," Maria Grajeda, *M.E.*, Vol. 55, 1997, p. 666.

"Make Your Own Ultrasonic Calculator," Dan Marks, *M.E.*, Vol. 54, 1996, p. 814-816.

"Manual Processing of Pipe Weld Radiographs," Robert F. Plumstead, *M.E.*, Vol. 53, 1995, p. 1278.

"Masking Radiographs," Bahman Zoofan, *M.E.*, Vol. 61, 2003, p. 409.

"Material Loss in Close Tolerance Holes, Processing," Grant Crawford, *M.E.*, Vol. 58, 2000, p. 1383.

"Measuring Discontinuity Depth of Butt Welds," Bahman Zoofan, *M.E.*, Vol. 62, 2004, p. 59.

"MT Bath Solution with a Refractometer, Maintain Water-Based," Maria Grajeda, *M.E.*, Vol. 55, 1997, p. 666.

"MT Problem," George Henke, *Tech Hints, M.E.*, Vol. 36, September 1978, p. 84.

"MT Problem," George Henke, *Tech Hints, M.E.*, Vol. 37, March 1979, p. 39.

"Multiple Radiographs Using a Single Film," Arthur Hoff, *M.E.*, Vol. 57, 1999, p. 830.

"NDT Uses for Tape, Two," Claude Lord, *M.E.*, Vol. 53, 1995, p. 1179.

"NDT, Using Thermographic NDT as an Example, Practical (Nontechnical) Aspects of," Douglas D. Burleigh, *M.E.*, Vol. 54, 1996, p. 1266.

"No More Tangled Lines," Bill Perrin, *M.E.*, Vol. 55, 1997, p. 804.

"Particle Concentration, Dealing with," Tom Larkin, *M.E.*, Vol. 59, 2001, p. 1087.

"Penetrant Density Chart," Jim Davis, *Tech Hints, M.E.*, Vol. 38, May 1980, p. 20.

"Penetrant and Magnetic Particle Proof," Terry Hurst, *M.E.*, Vol. 53, 1995, p. 488.

"Penetrant, Damp Cloth in Sealable Plastic Bags for Removal of Excess Water Washable," William C. Plumstead, *M.E.*, Vol. 60, 2002, p. 149.

"Penetrant Dye Removal," George Henke, *M.E.*, Vol. 56, 1998, p. 969.

"Penetrant Inspection, Acid Etching — An Alternative for Localized," Roger W. Engelbart, *M.E.*, Vol. 53, 1995, p. 402.

"Photographs of Reference Test Panels for Fluorescent Penetrant Testing," P. DuBosc, *M.E.*, Vol. 60, 2002, p. 703.

"Pipe Weld Radiographs, Manual Processing of," Robert F. Plumstead, *M.E.*, Vol. 53, 1995, p. 1278.

"Positive ID," Dan Marks, *M.E.*, Vol. 53, 1995, p. 1377.

"Practical (Nontechnical) Aspects of NDT, Using Thermographic NDT as an Example," Douglas D. Burleigh, *M.E.*, Vol. 54, 1996, p. 1266.

"Presenting Radiography to Larger Audiences," Claude Lord, *M.E.*, Vol. 59, 2001, p. 1278.

"Processing Material Loss in Close Tolerance Holes," Grant Crawford, *M.E.*, Vol. 58, 2000, p. 1383.

"Protected Centrifuge Tube," George Henke, *M.E.*, Vol. 57, 1999, p. 660.

"Quick and Easy Disbond Location," Arthur W. Irvine, *M.E.*, Vol. 53, 1995, p. 1278.

"Quick Eddy Current Inspection of Aircraft Wheels," Arthur W. Irvine, *M.E.*, Vol. 55, 1997, p. 573.

"Radiographic Contrast on Barely Visible Corrosion in Aircraft Structures, Improving," George Crowe, *M.E.*, Vol. 59, 2001, p. 1178.

"Radiographic Exposures, Foolproof," William C. Plumstead, *M.E.*, Vol. 55, 1997, p. 1153.

"Radiographic Film Cassette Holder, Flexible," Andrew Boyer, *M.E.*, Vol. 58, 2000, p. 427.

"Radiographic Identification, Easy," Andrew Boyer, *M.E.*, Vol. 59, 2001, p. 880.

"Radiographic Sensitivity Determination," Ed Trotter, *M.E.*, Vol. 60, 2002, p. 1358.

"Radiographs, Manual Processing of Pipe Weld," Robert F. Plumstead, *M.E.*, Vol. 53, 1995, p. 1278.

"Radiographs Using a Single Film, Multiple," Arthur Hoff, *M.E.*, Vol. 57, 1999, p. 830.

"Radiography and Planar Discontinuities," Bahman Zoofan, *M.E.*, Vol. 63, 2005, p. 821.

"Radiography, Balloon-Aided," Stuart Kleven, *M.E.*, Vol. 54, 1996, p. 587.

"Radiography of Test Coupons," Nathan Wade, *M.E.*, Vol. 61, 2003, p. 1125.

"Radiography — No Longer a Pain in the Back, Gamma," John Woollven, *M.E.*, Vol. 54, 1996, p. 816.

"Radiography Size Indicator," George Henke, *M.E.*, Vol. 55, 1997, p. 804.

"Radiography to Larger Audiences, Presenting," Claude Lord, *M.E.*, Vol. 59, 2001, p. 1278.

"Reducing Streaks on Processed Film," Syl Viaclovsky and Jean Staton, *M.E.*, Vol. 58, 2000, p. 645.

"Refractometer, Maintain Water-Based MT Bath Solution with a," Maria Grajeda, *M.E.*, Vol. 55, 1997, p. 666.

"Removal of Excess Liquid Penetrant on Rough Surfaces," William C. Plumstead, *M.E.*, Vol. 59, 2001, p. 1376.

"Residual Stress Measuring X-Ray Diffractometer, A Simple Method to Examine the Alignment of a," Claudia Kropas-Hughes and Edward Klosterman, *M.E.*, Vol. 60, 2002, p. 90.

"Resolution with an Analog Display, D-Meter," John N. Armstrong, *M.E.*, Vol. 54, 1996, p. 816.

"Resolving Inaccessible Back Surfaces during Ultrasonic Testing," Robert F. Clark, *M.E.*, Vol. 60, 2002, p. 1033.

"Rough Surfaces, Removal of Excess Liquid Penetrant on," William C. Plumstead, *M.E.*, Vol. 59, 2001, p. 1376.

"RT Enlargement/Flaw Sizing," George Henke, *M.E.*, Vol. 55, 1997, p. 986.

"RT Problem," Franics R. Berry, *Tech Hints, M.E.*, Vol. 37, July 1979, p. 58.

"RT Problem," George Henke, *Tech Hints, M.E.*, Vol. 36, August 1978, p. 53.

"RT Problem," George Henke, *Tech Hints, M.E.*, Vol. 36, October 1978, p. 56.

"RT Problem," George Henke, *Tech Hints, M.E.*, Vol. 36, November 1978, p. 21.

"RT Problem," George Henke, *Tech Hints, M.E.*, Vol. 38, July 1980, p. 55.

"RT Subject Contrast," George Henke, *M.E.*, Vol. 53, 1995, p. 588.

"Search Unit Adapter," George Henke, *M.E.*, Vol. 54, 1996, p. 422.

"Search Unit, 'Unrock' Your," George Henke, *M.E.*, Vol. 55, 1997, p. 1233.

"Second Cassette to Assure Correct Long Exposures," William C. Plumstead, *M.E.*, Vol. 60, 2002, p. 420.

"Shearography Inspection, Tip for the ESPI/," John Tyson, *M.E.*, Vol. 57, 1999, p. 443.

"Signal Confusion, Cutting," Stuart Kleven, *M.E.*, Vol. 54, 1996, p. 52.

"Simple Low-Cost Ultrasonic Plotter," Godfrey Hands, *M.E.*, Vol. 53, 1995, p. 1278.

"Size Indicator, Radiography," George Henke, *M.E.*, Vol. 55, 1997, p. 804.

"Sizing, RT Enlargement/Flaw," George Henke, *M.E.*, Vol. 55, 1997, p. 986.

"Smart Dollars — Those Saved While Helium Leak Testing," Charles N. Jackson, Jr., *Tech Hints, M.E.*, Vol. 42, 1984, p. 1076.

"Source Location, Accurate," Richard Gerhard, *M.E.*, Vol. 54, 1996, p. 1024.

"Specific Angle Protractor," George Henke, *M.E.*, Vol. 61, 2003, p. 484.

"Stabilizing Radiographic Film in Pipes," Bahman Zoofan, *M.E.*, Vol. 61, 2003, p. 588.

"Straight Arrow," George Henke, *M.E.*, Vol. 53, 1995, p. 1377.

"Straight Beam Index Point," George Henke, *M.E.*, Vol. 54, 1996, p. 814.

"Tape, Two NDT Uses for," Claude Lord, *M.E.*, Vol. 53, 1995, p. 1179.

"Tech Tip Sample, A," Claude S. Hendzel, *M.E.*, Vol. 53, 1995, p. 126.

"Temporary Parts Dryer," Bill Perrin, *M.E.*, Vol. 60, 2002, p. 552.

"Thermographic NDT as an Example, Practical (Nontechnical) Aspects of NDT, Using," Douglas D. Burleigh, *M.E.*, Vol. 54, 1996, p. 1266.

"Thermography Identifies Damaged Capacitors, Infrared," Paul Grover and Craig K. Kelch, *M.E.*, Vol. 54, 1996, p. 587.

"Tie Your Cables," George Henke, *M.E.*, Vol. 56, 1998, p. 1390.

"Tight Spot, Ultrasonic Techniques in a," Arthur W. Irvine, *M.E.*, Vol. 55, 1997, p. 1153.

"Timing Your Defect Locations," John Woollven, *M.E.*, Vol. 54, 1996, p. 422.

"Tip for the ESPI/Shearography Inspection," John Tyson, *M.E.*, Vol. 57, 1999, p. 443.

"Transducers, Hanging on to Tricky," Robert Saunders, *M.E.*, Vol. 53, 1995, p. 488.

"Two NDT Uses for Tape," Claude Lord, *M.E.*, Vol. 53, 1995, p. 1179.

"Ultrasonic Calculator, Make Your Own," Dan Marks, *M.E.*, Vol. 54, 1996, p. 814-816.

"Ultrasonic Couplants," Richard L. Tiefenauer, *M.E.*, Vol. 55, 1997, p. 192.

"Ultrasonic Plotter, Simple Low-Cost," Godfrey Hands, *M.E.*, Vol. 53, 1995, p. 1278.

"Ultrasonic Techniques in a Tight Spot," Arthur W. Irvine, *M.E.*, Vol. 55, 1997, p. 1153.

"Unrock Your Search Unit," George Henke, *M.E.*, Vol. 55, 1997, p. 1233.

Untitled, George Henke, *M.E.*, Vol. 56, 1998, p. 82.

"Using Intensifier Screens to Secure Film," Bahman Zoofan, *M.E.*, Vol. 61, 2003, p. 924.

"UT Angles," George Henke, *M.E.*, Vol. 53, 1995, p. 588.

"UT Cable, Extendable," Randy Lachermeier, *M.E.*, Vol. 53, 1995, p. 1179.

"UT Problem," John J. France, *Tech Hints, M.E.*, Vol. 37, April 1979, p. 32.

"U/T Problem," George Henke, *Tech Hints, M.E.*, Vol. 36, June 1978, p. 71.

"UT Problem," George Henke, *Tech Hints, M.E.*, Vol. 37, January 1979, p. 61.

"UV?, How Do You Measure," Con Murren, *M.E.*, Vol. 55, 1997, p. 986.

- "Watch Where You're Going," Godfrey Hands, *M.E.*, Vol. 53, 1995, p. 588.
- "Water Washable Penetrant, Damp Cloth in Sealable Plastic Bags for Removal of Excess," William C. Plumstead, *M.E.*, Vol. 60, 2002, p. 149.
- "Weld Inspection, A New Angle for," William C. Plumstead, *M.E.*, Vol. 53, 1995, p. 488.
- "Wheels, Quick Eddy Current Inspection of Aircraft," Arthur W. Irvine, *M.E.*, Vol. 55, 1997, p. 573.
- "Wire Splice, Low Profile," J.C. Doyle, *M.E.*, Vol. 57, 1999, p. 443.
- "X-Ray Centering with a Laser Pointer," Daniel Mace, *M.E.*, Vol. 57, 1999, p. 1069.
- "X-Ray Diffractometer, A Simple Method to Examine the Alignment of a Residual Stress Measuring," Claudia Kropas-Hughes and Edward Klosterman, *M.E.*, Vol. 60, 2002, p. 90.